


Example Defect – Identified in Lawrence (June 3rd, 2014)



**Discharge Location
(into the sanitary
sewer)**

**Sump
Pump
Location**