912 Chalk Hill Court - 07/09/2015 (search warrant/inspection)

Entry level, living room – ceiling shows evidence of water leaking/staining:





Upper level, master bedroom (north)



Upper level, South bedroom, (portion of ceiling fallen)









Lower level, hallway leading into bathroom and bedroom (mold and carpet saturated)



Bedroom, lower level, carpet saturated:






Bathroom, lower level, water on floor, mold








Dining area / sliding door, carpet saturated and mold on walls





Kitchen, lower level







Garage









Posting of search warrant on front door






Warrant posting, front door

912 Chalk Hill Court (exterior), 07/09/2015 (search warrant/inspection)



South elevation, rotten chimney chase





Rear view, east elevation



Rear sliding door (lower level), sill plate rotted out.





North side and west side (front)







