



Improvements have been made at the Disc Golf Course at Centennial Park to improve the overall conditions of the course. A layer of compacted ag-lime has been added at each hole to hold up to the foot traffic close to the baskets. In the past, the area has become very muddy after it has rained.





