


Photo Album for Lawrence, KS

Job 21580-01

February 13, 2009


This week the cab finished on the cab line and has been merged with the chassis along with the pump house and torque box. The body finished in paint and was staged to begin on the body line where harnessing and trim are added. Next week the chassis should begin on the main assembly line where the body and water tank should be merged with the chassis.




DSC00001



DSC00002



DSC00003



DSC00004



DSC00005



DSC00006



DSC00007



DSC00008



DSC00009



DSC00010



DSC00011



DSC00012



DSC00013



DSC00014



DSC00015



DSC00016



DSC00017



DSC00018



DSC00019



DSC00020



DSC00021




DSC00022



DSC00023



DSC00024



DSC00025



DSC00026



DSC00027



DSC00028



DSC00029



DSC00030



DSC00031



DSC00032



DSC00033



DSC00034




DSC00035



DSC00036



DSC00037



DSC00038



DSC00039



DSC00040



DSC00041



DSC00042




DSC00043



DSC00044



DSC00045



DSC00046




DSC00047



DSC00048



DSC00049



DSC00050




DSC00051



DSC00052



DSC00053



DSC00378



DSC00379



DSC00380



DSC00381



DSC00382