

1106 Rhode Island Street, 2/22/2012 (house pictures)



South view, roof, chimneys, broken windows, etc.





Front porch/supports



North view/foundation wall



North wall, shows separation between original structure and addition





Rear porch



Interior of house

Kitchen:



Bathroom



Back porch



1<sup>st</sup> Floor – middle living area:





Living room – front room (1<sup>st</sup> floor)



Stairway – to 2<sup>nd</sup> floor:



Front/west bedroom – 2<sup>nd</sup> level:



Bedroom (east) – 2<sup>nd</sup> level



Basement



1106 Rhode Island Street, 2/22/2012 - Accessory structures adjacent to alley:



Accessory structures – main (north and east end of property)







Small shed - SE corner of property





1106 Rhode Island Street, 2/22/2012

Misc. storage and abandoned vehicles in rear yard:

